



MARUYAMA 33L/MIN PUMP

APM0330R



REGULATOR PARTS



Rapid Spray Parts Breakdown

#	Description	Qty
1	CPUXK330S - Oil Filter Cap incl. #2	1
2	O-Ring P20	1
CPUXL330V - Valve Repair Kit		
3	Plug	1
4	O-Ring P20	1
5	#6204 Bearing	1
6	#6006 Bearing	1
7	D30428 Oil Seal	1
8	S100 O-Ring	1
9	Snap Ring	1
10	Oil Gauge incl. #10-2	1
11	Packing	1
12	17x24xT1.2 Washer	3
13	S10.5247 Oil Seal	3
14	Seal Retainer	3
15	10x19x5 Oil Wick	3
16	A Block incl #16-1 - 16-7	3
17	Inlet Valve Set	3
18	Piston Packing Set	3
19	6x8.5x10.5 Spacer	3
20	Piston Retainer	3
21	M6 Spring Washer	3
22	M6 Nut	3
CPUXK330G - Plunger Kit		
18	Piston Packing Set	3
22	M6 Nut	3
23	P21 O-Ring	6
24	P22 O-Ring	6
CPUXK330S - Seals Kit		
25	Valve Seat	3
26	Valve Sack Retainer	3
27	16x1.5 Valve	3
28	0.6-15L Spring	3
CPUXK330R - Regulator Repair Kit		
29	M3xP0.5x5 Screw	2
30	M4x6 Hexagon Socket Screw	1
31	16x21x0.7T Washer	1
32	15xT2.5 Spring Seat	1
33	3.0-31L Spring	1
34	0.6 - 7L Spring	1
35	5/32 Valve Ball	1
36	Piston Assembly	1
37	Sleeve	1
38	P16 O-Ring	1
39	Valve Seat	1